



Phoenix Contact Inc.  
P.O. BOX 4100  
Harrisburg, PA 17111-0100  
Phone: 717-944-1300

## Product Discontinuation

### PDN-ICC-8568-2023

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ICC - Industrial Cabinet	BE1	Product Discontinuation	Notify Distributors and Field	2/27/2023

*Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.*

Description for Product Discontinuation
Discontinuation for strategic reasons with replacement item

Stock Status
Can existing stock still be used?      Yes
Is mixture of stock acceptable?      No

Transaction Dates
Last Buy from Phoenix Contact:      2/29/2024
Last Scheduled Ship from Phoenix Contact:      5/30/2024

*Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.*

**Contact Info:**  
Chance Atkins  
catkins@phoenixcontact.com

Thank you,

\_\_\_\_\_  
Cory Myer  
Associate Product Marketing Manager ICC

## Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
1401019	MBK	3248025	MUT 1,5
1414006	MBK 2,5/E		
1414019	MBK 2,5/E BU		
1402788	MBK 2,5/E-PE		
1413010	MBK 3	3248030	MUT 2,5
1413094	MBK 3 BU	3248031	MUT 2,5 BU
1413036	MBK 3/E-Z	3248030	MUT 2,5
1413078	MBK 3/E-Z BU	3248031	MUT 2,5 BU
1413117	MBK 3/E-Z-PE	3248032	MUT 2,5-PE
1415018	MBK 5	3248035	MUT 4
1415092	MBK 5 BU	3248036	MUT 4 BU
1415076	MBK 5/E	3248035	MUT 4
1415115	MBK 5/E BU	3248036	MUT 4 BU
1415089	MBK 5/E-TG		
1402940	MBK 5/E-Z	3248035	MUT 4
1402982	MBK 5/E-Z BU	3248036	MUT 4 BU
0452043	MBK 5/E-Z -PE	3248037	MUT 4-PE
1402092	MBK 10 BU	3248038	MUT 6
1402225	ATS-MBK	1413227	ATP-MBK
1414035	D-MBK 2,5/E		
1414022	D-MBK 2,5/E BU		
1413023	D-MBK 3/5	3248033	D-MUT 2,5/4
1413104	D-MBK 3/5 BU	3248034	D-MUT 2,5/4 BU
1413706	D-MBK 5/E-T	3248033	D-MUT 2,5/4
1413049	D-MBK 6/E	3248033	D-MUT 2,5/4
1415021	D-MBK/E	3248033	D-MUT 2,5/4
1415102	D-MBK/E BU	3248034	D-MUT 2,5/4 BU
1418073	MBK 5/E-FS		
1418112	MBK 5/E-FS BU		
1417074	MBK 5/E-FS/FS		
1407013	MBK-FS		
1407097	MBK-FS BU		
1406014	MBK-FS/FS		
1406098	MBK-FS/FS BU		
0452027	MSLKG 2,5		
0552024	MBK 6/E	3248038	MUT 6
1402018	MBK 10	3248038	MUT 6
0452014	MSLKG 5	3248037	MUT 4-PE
0801791	TP-BK/MBK		
1401093	MBK BU		
1410505	MSLKG 6		