



Product Change Notice

PCN Number: 14-0834-01
Issue Date: 28-AUGUST-2014

Exar Corporation
www.exar.com | Support: customersupport@exar.com

PRODUCTS AFFECTED:

XRP7725ILB-F

XRP7725ILBTR-F

XRP7725ILBMTR-F

CHANGE CATEGORY: Material Process Package Design Datasheet Packing/Shipping Other: Patch-code update**DESCRIPTION OF CHANGE:**

The XRP7725 has been changed to meet the datasheet functional description for Group 0 assigned outputs. Prior to the change those Group 0 outputs would not self-enable after internal loading of the configuration registers. This has been corrected and Group 0 outputs automatically enable after internal registers are loaded.

IMPACT OF CHANGE:

XRP7725 now meets datasheet functional description for Group 0 channels.

TARGET IMPLEMENTATION DATE: 28-AUGUST-2014

*Please contact customer support (customersupport@exar.com) for sample date availability or qualification data.

PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.