Product/Process Change Notifications



PCN - 14 073

7				Release Date: September 22 2014	
Product Name:	SFP+ BOARD CONN ASSY				
	SFP+ BOARD CONN ASSY				
Product Manager:	Lynn Zhou				
Subject:	Notification of Change with Immediate Effectivity				
Distribution	General				
Type of Change:	Design Change				
Change Description:	There are four pin numbers 1,10,11,20 pin number 1 moved to the left of the housing is the only available marking. 1) Correct the wrong spelling specification numbers in GS-20-0385. Product Specification: GS-12-1411 (before change) → GS-12-1141(after change); Package Specification: GS-14-1399(before change) → GS-14-2372(after change). 2) Correct the wrong spelling specification numbers in customer drawing. Package Specification: GS-14-1399(before change) → GS-14-2372(after change).				
Reason for Change:	Correct the wrong pin location mark on the housing and spelling errors.FCI decides immediately make effective this PCN in to avoid any misunderstanding on the pin location at customer side				
Affected Parts:	10122424-101L/10122424-901LF				
Effective Date of Change:	September 30, 2015				
Last Time Buy Date:	NA				
Last Disty Return Date:	NA				
Last Time Shipment Date		NA T			
Datasheet Attached?	No				
Qual/Test Data Attached?	No				
Samples Availability Date:	September	22	2014		
Available Alternatives?	N/A				
Questions?	Contact your local FCI Representative, or Product Manager				
	Lynn Zhou/ Product Manager-Dongguan site				
	86-769-88682108 Ext: 603 / ZhouLy @fci.com				

Note:

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date. PCN is considered approved by the customer if no communication is received within 3 weeks