

Automotive Product Discontinuance Notification

Date: June 27, 2012

EOL Reference: EOL507

Product Reference: Various Automotive Technologies

To Our Valued Customer:

We appreciate your use of International Rectifier (IR) semiconductor products. Our commitment to customer satisfaction and continuous improvement is demonstrated by our plans to enhance capacity, quality and reliability. We would like to express our sincere appreciation for your cooperation regarding the following changes, and IR will work closely with you to support your requirements during this transition.

Reason for Product Discontinuance:

Product portfolio rationalization and lack of demand.

Products Affected:

EOL Part	Replacement Part	EOL Part	Replacement Part
62-0041PBF	n/a	94-4097PBF	n/a
62-0042PBF	n/a	94-4104PBF	n/a
62-0043	n/a	94-4188	n/a
62-0045	n/a	94-4222	n/a
62-0142PBF	n/a	94-4296	n/a
62-0145	n/a	94-4302PBF	n/a
62-0171PBF	n/a	94-4303PBF	n/a
62-0172PBF	n/a	94-4304PBF	n/a
64-0000	n/a	94-4307PBF	n/a
64-0001	n/a	94-4309	n/a
64-0003	n/a	94-4312	n/a
64-0007PBF	n/a	94-4312PBF	n/a
64-0035PBF	n/a	94-4345	n/a
64-2011	n/a	94-4373PBF	n/a
64-2012	n/a	94-4375	n/a
64-2022	n/a	94-4397	n/a
64-2044	n/a	94-4583PBF	n/a

International Rectifier

101 N. Sepulveda Blvd., El Segundo, CA 90245 USA

Telephone: +1 310 726 8000

www.irf.com

64-2058	n/a	94-4583T	n/a
64-2099PBF	n/a	94-4585	n/a
64-2106PBF	n/a	94-4586	n/a
64-4023	n/a	94-4587	n/a
64-4026	n/a	94-4591	n/a
64-4051PBF	n/a	94-4601PBF	n/a
64-4058	n/a	94-4611	n/a
64-4072	n/a	94-4744	n/a
64-4093PBF	n/a	94-4748PBF	n/a
64-4107PBF	n/a	94-4752	n/a
64-4108PBF	n/a	94-4757	n/a
87-4546	n/a	94-4797	n/a
94-2009	n/a	94-4799	n/a
94-2040	n/a	94-4805	n/a
94-2043	n/a	94-4815	n/a
94-2049	n/a	94-4818	n/a
94-2051	n/a	94-4820	n/a
94-2107	n/a	94-4821	n/a
94-2112	n/a	94-4826	n/a
94-2125	n/a	94-4894	n/a
94-2126	n/a	94-4923	n/a
94-2176	n/a	94-4924PBF	n/a
94-2187	n/a	98-0059	n/a
94-2205	n/a	98-0063	n/a
94-2206PBF	n/a	98-0177	n/a
94-2209	n/a	98-0180	n/a
94-2216	n/a	98-0227B	n/a
94-2224	n/a	98-0271	n/a
94-2237	n/a	98-0305PBF	n/a
94-2297	n/a	98-0321	n/a
94-2311	n/a	98-0455PBF	n/a
94-2342	n/a	98-0472STPBF	n/a
94-2360	n/a	98-0481TPBF	n/a
94-2363	n/a	AUIRS2016S	AUIRS20161S
94-2365	n/a	AUIRS2016STR	AUIRS20161STR
94-2371	n/a	IPS1011PBF	AUIPS1011
94-2372	n/a	IPS1011RPBF	AUIPS1011R
94-2381	n/a	IPS1011RTRLPBF	AUIPS1011RTRL
94-2413	n/a	IPS1011RTRRPBF	AUIPS1011RTRR
94-2428	n/a	IPS1011SPBF	AUIPS1011S

International Rectifier

101 N. Sepulveda Blvd., El Segundo, CA 90245 USA Telephone: +1 310 726 8000 www.irf.com

94-2438	n/a	IPS1011STRLPBF	AUIPS1011STRL
94-2444	n/a	IPS1011STRRPBF	AUIPS1011STRR
94-2495	n/a	IPS1021PBF	AUIPS1021
94-2519	n/a	IPS1021RPBF	AUIPS1021R
94-2543	n/a	IPS1021RTRLPBF	AUIPS1021RTRL
94-2554	n/a	IPS1021RTRRPBF	AUIPS1021RTRR
94-2645	n/a	IPS1021SPBF	AUIPS1021S
94-2856	n/a	IPS1021STRLPBF	AUIPS1021STRL
94-2858	n/a	IPS1021STRRPBF	AUIPS1021STRR
94-2868	n/a	IPS1031PBF	AUIPS1031
94-2916	n/a	IPS1031RPBF	AUIPS1031R
94-2930	n/a	IPS1031RTRLPBF	AUIPS1031RTRL
94-2939	n/a	IPS1031RTRRPBF	AUIPS1031RTRR
94-3123PBF	n/a	IPS1031SPBF	AUIPS1031S
94-3205	n/a	IPS1031STRLPBF	AUIPS1031STRL
94-3252PBF	n/a	IPS1031STRRPBF	AUIPS1031STRR
94-3358	n/a	IPS1041LPBF	AUIPS1041L
94-3359	n/a	IPS1041LTRPBF	AUIPS1041LTR
94-3430PBF	n/a	IPS1041RPBF	AUIPS1041R
94-3447	n/a	IPS1041RTRLPBF	AUIPS1041RTRL
94-3449	n/a	IPS1041RTRRPBF	AUIPS1041RTRR
94-3451	n/a	IPS1042GPBF	AUIPS1042G
94-3629	n/a	IPS1042GTRPBF	AUIPS1042GTR
94-3639	n/a	IPS1051LPBF	AUIPS1051L
94-3643	n/a	IPS1051LTRPBF	AUIPS1051LTR
94-3646PBF	n/a	IPS1052GPBF	AUIPS1052G
94-3647	n/a	IPS1052GTRPBF	AUIPS1052GTR
94-3652	n/a	IR3411SPBF	n/a
94-4008	n/a	IR3411STRPBF	n/a
94-4059PBF	n/a	IRF7341Q	AUIRF7341Q
94-4091PBF	n/a	IRSF3010STRR	N/A

Effective Dates:

- Customer Notice: June 27, 2012
- Last Time Buy: December 27, 2012
- Last Schedule Shipment: June 27, 2013
- Final Return Date: September 27, 2012
- Expiration of Ship & Debit: September 27, 2012

International Rectifier

101 N. Sepulveda Blvd., El Segundo, CA 90245 USA Telephone: +1 310 726 8000 www.irf.com

Alternate or Replacement Product:

Please refer to table for suggested replacements.

Contact Information:

CONTACT	NAME	PHONE	EMAIL
Business Manager	Miriam Heath	+1 951 375-4110	mheath1@irf.com
Sr. Business Manager	Kenny Kang	+1 951 375 2132	kkang1@irf.com