

We are announcing the phase-out of the following **AMAX-5057SO-A** modules:

- **Reason:** Fixing bug of “potential no output at DOs” issue. (DO: Digital Output)
- **Replacement:** This “-A” model will be replaced by “-A2” model.

End of Life Product	Suggest Replacement Product
AMAX-5057SO-A	AMAX-5057SO-A2