



PRODUCT OBSOLESCENCE MEMO

MULTIFUSE® PPTC RESETTABLE FUSES



Bourns to Discontinue Model MF-R/90 Series

Riverside, California – January 20, 2020 – In accordance with our ongoing product lifecycle management, Bourns will be discontinuing the [Multifuse® MF-R/90 series](#). Diminishing demand necessitates this action. The affected part numbers are shown in the table below.

Obsolete Part Numbers	Alternatives
MF-R055/90-0	For information about possible replacement products, contact Bourns Customer Service
MF-R055/90-2	
MF-R055/90-2-17	
MF-R055/90-AP	
MF-R055/90-AP-17	
MF-R055/90U-0	
MF-R055/90U-2	
MF-R055/90U-AP	
MF-R075/90-0	
MF-R075/90-2	
MF-R075/90-2-17	
MF-R075/90-AP	
MF-R075/90-AP-17	

Customers must notify Bourns in writing within 30 days of publication of this notification if they consider the discontinued product to be sole sourced by Bourns. In such cases, Bourns will work to negotiate an appropriate end-of-life purchase for the discontinued products. Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. All orders placed for these products between the publication of this obsolescence notification and the last time buy date will be considered non-cancellable and non-returnable.

Please plan for the following deadlines:

Last Time Buy Date: **September 26, 2020**

Last Time Ship Date: **December 19, 2020**

Should you have any questions or need additional information, please feel free to contact [Bourns Customer Service](#).

MF1953