

Global Change Notification (GCN)

Product Family	040 W/B FEMALE HSG ASSY-16P / 20P	10743413
		GCN Number
Series	35563 / 35564	January 07, 2016
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The purpose of this letter is to inform you that copy molds of retainer for 355631615, 355642015 and 355642016 will be implemented. The retainer is one of component for terminal position assurance. These additional toolings are needed in order to keep up with current and future demands of these products. There will be no change in product form, fit, or function. Implementation Date may be changed due to customer demand and production situation.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	No impact to fit, form or function as a result of this change. Test report can be supplied at your request and can be communicated through your local Molex Sales Representative.	
Internal Molex Qualification Date (Planned Date Information Available)	January 10, 2016	
Sample Availability Date (Changed Part)	January 10, 2016	
Date of Implementation	February 01, 2016	
Method of Identifying Change	Lot information in the label	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com