

PRODUCT BULLETIN

Supply Chain Raw Material shortage affecting CSA certification on VT Models; 1010, 1210, & 1220

October 15, 2021,

Bulletin #10

The update on the material shortage that directly affected the timely shipment of our variable transformer models 1010, 1210, and 1220 required approval of an alternate source. This new source will start arriving for use in late November with delivery starting after December 1, 2021. This is an isolated issue, and these are the only model numbers affected. We are fully committed to being your long-term supplier for all your autotransformer needs.

Our variable products remain designed to the CSA 22.2 standards. The electrical and mechanical design and function have not changed. The new polymeric material for the unit base has not been evaluated within our design to the CSA standards 22.2.

As part of the decision to supply units quickly, the initial product cannot be marked and listed CSA until paperwork is approved by CSA. New part numbers will utilize a suffix “N” for the NON-CSA product that will be available in December for shipment.

CURRENT	NEW	CURRENT	NEW
CSA P/N	NON-CSA P/N	CSA P/N	NON-CSA P/N
1010B	1010B-N	1210B	1210B-N
3PN1010B	3PN1010B-N	3PN1210B	3PN1210B-N
L1010B	L1010B-N	1210B-2	1210B-2-N
1010B-2	1010B-2-N	1210B-3	1210B-3-N
1010B-3	1010B-3-N	1220B	1220B-N
1020B	1020B-N	3PN1220B	3PN1220B-N

If you have any questions regarding the production delay of the 1010, 1210, and 1220 models please do not hesitate to contact Staco at Orders@stacoenergy.com or me on 937-253-1191 x 128 or at heiligenbergp@stacoenergy.com.

Sincerely,

Paul Heiligenberg,

Business Development Manager



Together We Power On