

Global Change Notification (GCN)

Product Family	SE	10716591	
		GCN Number	
Series	47337/78725/105028/105037/105091/105135/105174/105189	September 15, 2015	
		Date Issued	
Reason For Change	Obsolescence		
Change Description	The purpose of this letter is to inform you that the following 13 camera socket will be obsoleted due to old wear out tooling and Low demand to obtain suppliers support. LTB date is 2016/03/31, LTS date is 2016/9/30		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.		
Reason For Short Notice Exception	Not Applicable		
Assessment Of Change (How Product Will Be Qualified & Validated)	N/A		
Internal Molex Qualification Date (Planned Date Information Available)			
Sample Availability Date (Changed Part)			
Date of Implementation	September 30, 2016		
Method of Identifying Change	N/A		
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts	March 31, 2016		
Last Time Ship Date for Obsolete Parts	September 30, 2016		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com