

Product Discontinuation



PD_091_16

■ Last Order Date:	2017-03-30
■ Last Delivery Date:	2017-09-30

Reason: Discontinuation of the products TDA5230, TDA5231, TDA5340, TDA5212 and RX98-3

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	OPN	Package	Device	Ordering Code	OPN	Package
TDA5230	SP000076520	TDA5230XUMA1	PG-TSSOP-28-1	TDA5235	SP000507674	TDA5235XUMA1	PG-TSSOP-28-17
TDA5231	SP000202847	TDA5231XUMA1	PG-TSSOP-28-1	TDA5235	SP000507674	TDA5235XUMA1	PG-TSSOP-28-17
TDA5340	SP000803722	TDA5340XUMA1	PG-TSSOP-28-1	none			
TDA5212	SP000013430	TDA5212XUMA1	PG-TSSOP-28-1	TDA5235	SP000507674	TDA5235XUMA1	PG-TSSOP-28-17
RX98-3	SP000743710	RX983XUMA1	PG-TSSOP-28-1	TDA5201	SP000012902	TDA5201XUMA1	PG-TSSOP-28-17

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!