

Courtesy Notification

Issue Date: 18-July-2016

Change Type:

Package related change: Orientation mark change.

Parts Affected:

ALM-80110-TR1G
ALM-80110-BLKG
ALM-80210-TR1G
ALM-80210-BLKG

Description and Extent of Change:

Broadcom Limited is changing the cosmetic appearance of orientation marking on product. Please review diagram below for details. The rest of identification marking (device code, workweek, year code and assembly lot no) remains the same.

Reasons for Change:

This is part of Broadcom's continuous product improvement.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same. No change is expected to product characterization and reliability of product.

Effective Date of Change:

Product timing of shipment of the changed part will begin immediately.

Qualification Data:

Qualification data package is not applicable for this change.



These changes have been reviewed and approved by Broadcom Limited engineers and managers per Broadcom Limited' procedure: Change Control and Customer Notification, 5962-6052-80.

Please contact your Broadcom Limited field sales for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.