

IIoT Product Change Notice



The change will be applied on the ULI-342TC (BB-USOPTL4DR-2). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

Note: The ordering process has not been changed. Customers should continue to order model number BB-USOPTL4DR-2.

- Reason for the Change:** Branding & Compliance Marking. The UL File Number will change from E222870 to E327848.
- Affected Products:** ULI-342TC (BB-USOPTL4DR-2)
- Impact on Application:** No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	YES
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-342TC BB-USOPTL4DR-2	20BB250-10924-00	1990034365T010	Label	<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Old Name Plate</p>  </div> <div style="text-align: center;"> <p>New Name Plate</p>  </div> </div>	Branding

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ULI-342TC (BB-USOPTL4DR-2)	ECOM-194497	12/14/2022	Running Change	Update name plate and UL File number.

*Note: Cut-in progress depends on factory production schedule.

** Note: The ordering process has not been changed. Customers should continue to order model number BB- BB-USOPTL4DR-2.

Contact Windows

PM	Brian Foster / brian.foster@advantech.com
AE	N/A