

IloT Product Change Notice



The change will be applied on the ULI-361TK (BB-485USBTB2WLS-A). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

Note: The ordering process has not been changed. Customers should continue to order model number BB-485USBTB2WLS-A.

- Reason for the Change:** Branding
- Affected Products:** ULI-361TK (BB-485USBTB2WLS-A)
- Impact on Application:** No change to form, fit, or function.

| Item | Impact |
|---------------------------------------|--------------------------|
| Impact on Mechanical Design | No |
| Impact on Software Compatibility | No |
| Impact on Environment Characteristics | No |
| Impact on System Certifications | No |
| Physical Outlook Change | Yes |
| Ordering P/N Change | No |
| Cut-in Implement | Component Running Change |

4. Description of the Change(s):

| Affected Models | Current Component | New Component | Category | Outlook Difference | Reason |
|--------------------------------|----------------------|----------------|----------|---|----------|
| ULI-361TK BB-485USBTB2WLS-A | 20BB250- 10886-00 | 1990034354T050 | Label | <p>Old name plate</p>  <p>New name plate</p>  | Branding |

5. Implementation & Schedule of the Change(s):

| Affected Models | ECOM Number | Estimated Effective Date | Cut-in Implement | Change Description |
|-------------------------------|-------------|--------------------------|------------------|--------------------|
| ULI-361TK (BB-485USBTB2WLS-A) | ECOM-186952 | 9/20/2022 | Running Change | Update name plate. |

*Note: Cut-in progress depends on factory production schedule.

** Note: The ordering process has not been changed. Customers should continue to order model number BB-485USBTB2WLS-A

Contact Windows

| | |
|----|---|
| PM | Brian Foster / brian.foster@advantech.com |
| AE | N/A |