



# Update Notification

Document # : PD22094X8

Issue Date: 21 November 2018

<b>Title of Change:</b>	Update to PD22094X announcing the addition of recommended replacement.
<b>Last Time Buy Date:</b>	N/A
<b>Last Ship Date:</b>	N/A
<b>Contact information:</b>	Contact your local ON Semiconductor Sales Office or < <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >
<b>Type of notification:</b>	ON Semiconductor will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, contact < <a href="mailto:PCN.Support@onsemi.com">PCN.Support@onsemi.com</a> >.

**Description and Purpose:**

This is to formally inform customers of the addition of recommended replacement in PD22094X. LB11961-W-AH was added in the recommended replacement.

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel ([tom.siegel@onsemi.com](mailto:tom.siegel@onsemi.com))

☎ +1 765 868 5022

USA

Europe:

Andrej Tomasik ([andrej.tomasik@onsemi.com](mailto:andrej.tomasik@onsemi.com))

☎ +421 33790 2229

Slovakia

Japan:

Isao Usuki ([isao.usuki@onsemi.com](mailto:isao.usuki@onsemi.com))

☎ +81 3 5817 1060

Japan

Asia Pacific:

Stephen Ng ([stephen.ng@onsemi.com](mailto:stephen.ng@onsemi.com))

☎ +852 2689 0209

China

**List of Affected Standard Parts:**

Device to be Discontinued	Recommended Replacement	Supplier
LB11961-TLM-H-W	LV11961HA-AH LB11961-W-AH	ON Semiconductor



---

## Appendix A: Changed Products

---

---

Product	Customer Part Number	Replacement Parts	Replacement Suppliers
LB11961-TLM-H-W		LV11961HA-AH LB11961-W-AH	ON SEMICONDUCTOR