



# Product Change Notification

<b>Date Issued :</b>	May 11, 2022	<b>PCN Number :</b>	512016
<b>Reason for Change :</b>	Change Supplier		
<b>Description of Change :</b>	This notification is to inform you about changes that are being made to the part(s) as identified in the list. This change may result in a change to the raw material.		
<b>Reason for Short Notice :</b>	Special Request		
<b>Assessment of Change :</b>	Reliability Test Report/s First Article Inspection		
<b>Planned Implementation Date :</b>	August 01, 2022		
<b>Sample Availability Date:</b>	May 31, 2022		
<b>Internal Molex Qualification Date :</b>	May 31, 2022		
<b>Last date to request Samples by Customer :</b>	June 30, 2022		
<b>Traceability Code Markings / Date :</b>	New part number		

Before Picture

---

## BACKGROUND OF THIS PCN

- As we informed by the News Release on February 2, 2022, Toray industries, one of Molex's resin suppliers, announced it had improperly identified certain resin products as receiving certification from Underwriters Laboratories (UL), a global third-party safety science organization headquartered in the United States.
- <https://www.toray.com/global/news/details/20220131151731.html>
- As previously noted, products sold to you by Molex contain resins from Toray Industries, Inc. (collectively, the "Affected Toray Resins") that were inappropriately certified by Underwriters Laboratories (UL). Molex has since learned the Affected Toray Resins have their UL certifications revoked on March 31, 2022.
- Due to the reasons noted above, Molex has made the decision to stop shipping products that use the Affected Toray Resins as of March 8, 2022 unless an accommodation can be reached.
- This PCN is to inform you about the change from Toray resin to other UL94 V-0 resin, which we will implement to resume stable supply of these products.

© Molex, LLC


*creating connections for life*

**molex**

After Picture

## CHANGE OVERVIEW

- Change a resin material for 51281\*\*94 HOUSING



- Part Number Impact: 51281\*\*94.  
See attached impacted parts list for more detail.
- Product Impact: No impact to Form, Fit or Function.
- Identification: We will change the Part Numbers from 51281\*\*94 to 51281\*\*98.

Contents	Current	New
Part Number	51281**94	51281**98
Resin	TORAY LCP UL-94 V0 (Revocation)	SUMITOMO LCP UL-94 V0

- PPAP and samples available upon request

2 © Molex, LLC

*creating connections for life***molex**

# RELEASED

You may address inquires regarding this PCN by clicking on the below link  
[mailto:pcn\\_coordinator@molex.com?subject=PCN\\_Notification:512016](mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512016)  
 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512016** " in the e-mail Subject line for faster response.

**Molex, LLC**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL (800) 786-6539  
[www.molex.com](http://www.molex.com)

**PCN No Part List**

512016 [0512810594](#)

512016 [0512810694](#)

512016 [0512810794](#)

512016 [0512810894](#)

512016 [0512810994](#)

512016 [0512811094](#)

512016 [0512811194](#)

512016 [0512811294](#)

512016 [0512811494](#)

512016 [0512811694](#)

512016 [0512811894](#)

512016 [0512812094](#)

512016 [0512812294](#)

512016 [0512812494](#)

512016 [0512812694](#)