



# SIERRA WIRELESS PRODUCT CHANGE NOTICE

## OVERVIEW

<b>DATE ISSUED:</b>	April 1, 2020	<b>TRACKING NUMBER:</b>	4134764
<b>ISSUED BY:</b>	AirPrime Product Management		
<b>PRODUCTS AFFECTED:</b>	EM7455, MC7455, EM7430, MC7430		
<b>SKUS AFFECTED:</b>	1104355, 1103790, 1103789, 1103759, 1103578, 1103577, 1104354, 1104036, 1103780, 1103582, 1103579, 1103733, 1103732, 1103730, 1103731, 1103737, 1103743		
<b>BULLETIN:</b>	<i>Obsolete SKUs with replacement SKUs</i> <i>Improvements to FW quality, addresses bug fixes</i>		
<b>URGENCY:</b>	Normal		
<b>FOR DISTRIBUTION TO:</b>	Customers using SKUs affected.		

## Summary

As part of ongoing efforts to improve our firmware quality and address known field issues, SWI has released FW version 02.32.11.00 and newer, targeting all EM/MC74xx SKUs. FW version 02.32.11.00 and newer have already received respective carrier certifications, and is ready for deployment.

As a result, SWI will be obsoleting all MC/EM74xx SKUs with older FW versions on Sep 1<sup>st</sup>, 2020. Replacement SKUs are already available and ready to order. No hardware changes have been made, and all hardware components remain identical.

## Details of Change

Please refer to the Release Notes for the list of changes added to FW 02.32.11.00 or newer. Below are a list of replacement SKUs.

SKU #	Description	Replacement SKU #	Replacement SKU Description
1104355	MC7455,GENERIC,GENERIC/AT&T/BELL/ROGERS/SOUTHERNLINC/SPRINT/TELUS/VERIZON/VODAFONE,02.30.01.01,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M;QUALIFIED	1104636	MC7455,GENERIC,GENERIC/AT&T/BELL/ROGERS/SPRINT/TELUS/VERIZON/VODAFONE,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M;QUALIFIED
1103790	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M - B30 DISABLED	1104637	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M
1103789	MC7455,GENERIC,GENERIC/AT&T/BELL/ROGERS/SPRINT/TELUS/US CELLULAR/VERIZON/VODAFONE,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M; QUALIFIED	1104636	MC7455,GENERIC,GENERIC/AT&T/BELL/ROGERS/SPRINT/TELUS/VERIZON/VODAFONE,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M;QUALIFIED
1103759	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M; USB2.0	1104638	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M; USB2.0
1103578	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M	1104637	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M

1103577	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M - B30 DISABLED	1104637	MC7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M
1104354	EM7455,GENERIC,GENERIC/AT&T/BELL/ROGERS/SPRINT/TELUS/US CELLULAR/VERIZON/VODAFONE,02.30.01.01,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M;QUALIFIED	1104639	EM7455,GENERIC,GENERIC/AT&T/BELL/ROGERS/SPRINT/TELUS/VERIZON/VODAFONE,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M;QUALIFIED
1104036	EM7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,MBIM; M2M	1104640	EM7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M
1103780	EM7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M; QUALIFIED	1104639	EM7455,GENERIC,GENERIC/AT&T/BELL/ROGERS/SPRINT/TELUS/VERIZON/VODAFONE,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M;QUALIFIED
1103582	EM7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M	1104640	EM7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M
1103579	EM7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M - B30 DISABLED	1104641	EM7455,GENERIC,GENERIC/AT&T/SPRINT/VERIZON,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M - B30 DISABLED
1103733	EM7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M QUALIFIED	1104642	EM7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M QUALIFIED
1103732	EM7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M	1104643	EM7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M
1103730	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M	1104644	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M
1103731	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.24.05.06,,AVMS,GNSS=ABCD,NO IMEI,QMI,M2M	1104644	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M
1103737	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.24.05.06,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M QUALIFIED	1104645	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M QUALIFIED
1103743	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.24.05.06,,AVMS,GNSS=ABCD,NO IMEI,QMI,M2M QUALIFIED	1104645	MC7430,GENERIC,GENERIC/DOCOMO/KDDI/SOFTBANK/TELSTRA,02.33.03.00,,AVMS,GNSS=ABCD,SWIR IMEI,QMI,M2M QUALIFIED

Customers using the existing SKUs should replace with the newer replacement SKUs ASAP. Please contact your Sierra Wireless technical support person if you need certification guidance to update your certification to these latest FW.

FW 02.32.11.00 and newer packages and release notes are available on The Source.

### Timeline

- SKUs will obsolete on Sep 1<sup>st</sup>, 2020
- Replacement SKUs are already available.

### More information

For more information please contact your Sierra Wireless sales/technical support person.