

InnoSenT GmbH · Am Roedertor 30 · 97499 Donnersdorf

Tel. +49 (0) 9528 9518 - 0
 Fax +49 (0) 9528 9518 - 99
 E-Mail info@innosent.de



ISO TS 16949:2009
 ISO 9001:2008
 ISO 14001:2004

Donnersdorf, 02.07.2020

Announcement of product discontinuation

Dear Sir or Madame,

We would like to inform you about the discontinuation of the following device:

- iSYS-6003 and its derivatives.

The sensor is replaced by the iSYS-6030. This system is equivalent to the iSYS-6003 in terms of form, fit and function and is therefore a direct replacement. An adjustment of the customer circuitry is not necessary.

Milestones	
Affected products	iSYS-6003 iSYS-6003_ETB iSYS-6004 iSYS-6005 iSYS-6006 iSYS-6103_USB iSYS-6103_RS485 iSYS-6203
Effectiveness of discontinuation	02.07.2020
Direct Replacement product	iSYS-6030

Already placed orders are still served with the iSYS-6003.

Our sales team will be pleased to assist if you have any questions regarding this product discontinuation notice.

With kind regards



Christian Bömmel
 InnoSenT GmbH
 Head of Automotive & Industrial Business Unit