



TE Connectivity

Product Change Notification: E-15-003448 PCN Date: 04-MAR-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).


General Product Description:

040III TAB CONTACT 353537-1 and 353537-2.

Description of Changes

PN 353537-1 and 353537-2; Carrier area; Additional 1.5mm*5.5mm Punched Hole per 9.5 mm pitch. The crimping report will be released by Mar 20. If you have any question, please contact Ken Sakai san.





Reason for Changes:					
Product Improvement. Lighter weight of gross package and transportation.					
Estimated Dates:					
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	05-JUN-2015				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	05-SEP-2015				

Part Number(s) being Modified:

	-						
Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Part Number(s)	Difference
353537-1	NO						

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Numbe	rCurrent Revision	New Revision	Related Part Number	Customer Part Number
353537	A1		353537-1	