

Product End Of Life Notification			Date October 15, 2015
Product	EtherLite 2 port Notice # 151018-03		
Reason for Change :			
Technical Requirement		Product Transition	
Customer Requirement		Product Discontinua	ition
Quality Improvement		Product Enhanceme	nt
Change of Production	n Location	Other (Brand Chang	ge)
Description of change	The EtherLite 2 port product variation is being discontinued. The EtherLite 8 and 16 versions will remain active. This is an ongoing effort to streamline our product offerings to focus on consistent product availability while maintaining our high quality of product. This product also has several last time buy components that are becoming difficult to procure on this 20 year old product. There is limited availability of these products. Submit orders as soon as possible to ensure availability. All LTB purchase orders are NCNR (non-cancellable/non-returnable). Standard warranty policy will apply to all LTB purchases.		

Part Numbers	70001430 EtherLite 2
	70001531 EtherLite 2 Int'l

Timing of Change	Last time buy orders must be received by: February 15, 2016 Last time ship date for all confirmed orders: March 15, 2016
Replacement Product	Recommended Alternative: 70001430 → 70002043 PortServer TS 2 70001531 → 70002044 PortServer TS 2 Int'l
	EtherLite has different RJ45 serial pin-out than the PortServer products. However, each product uses the RealPort driver. Refer to product datasheets, user manuals and web info for additional information.
	http://www.digi.com/products/serial-servers/serial-device-servers/etherlite http://www.digi.com/products/serial-servers/serial-device- servers/portserverts

Last Time Buy Parts	Several, which includes the microprocessor, line drivers and RAM.	
Quality Issues	None	

Authorization	Kim Knutsen, Sr. Product Manager, Digi International