

## PRODUCT CHANGE NOTIFICATION

Product Category	COPPER - CABLE - 1G		_20200914-1				
Product Group	BULK COPPER CABLE			_			
ISSUE DATE:	9/14/2020			_			
IMPACTED REGIONS:	✓ NA	✓ EMEA	✓ LATAM	✓ AP	_		
REASON FOR CHANGE:	✓ DISCONTINUATION						
	OTHER						
DESCRIPTION OF CHANGE: (	Required)						
As a result of global rationalization and simplification of the Panduit copper cable portfolio, we have consolidated two products into							
one. Both products have sim	ilar attributes and func	tion. Please revie	w the product not	tification for a li	st of the affected parts.		
Photos/Drawing (where appl	licable)						
IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)							
5 6 6 4 1 1							

Reference Page 2 / Linked PDF

## DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

	Year	Month	Day
SCHEDULE FOR CHANGE	(YYYY)	(MM)	(DD)
New product sample availability date	2020	9	14
Old product discontinuation date*	2020	12	14

<sup>\*</sup>Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

Impacted Part Numbers	Replacement Part 1
PUR5C04BU-U	PUR5C04BU-F
PUR5C04WH-U	PUR5C04WH-F
PUP5C04BL-F	PUP5C04BL-U
PUP5C04IG-F	PUP5C04IG-U
PUP5C04GR-F	PUP5C04GR-U
PUP5C04RD-F	PUP5C04RD-U
PUP5C04OR-F	PUP5C04OR-U
PUP5C04VL-F	PUP5C04VL-U
PUP5C04YL-F	PUP5C04YL-U
PUP5C04BU-U	PUP5C04BU-F
PUP5C04WH-U	PUP5C04WH-F
PUR5C04BU-U-S	PUR5C04BU-F-S
PUR5C04WH-U-S	PUR5C04WH-F-S
PUP5C04BL-F-S	PUP5C04BL-U-S
PUP5C04IG-F-S	PUP5C04IG-U-S
PUP5C04GR-F-S	PUP5C04GR-U-S
PUP5C04RD-F-S	PUP5C04RD-U-S
PUP5C04OR-F-S	PUP5C04OR-U-S
PUP5C04VL-F-S	PUP5C04VL-U-S
PUP5C04YL-F-S	PUP5C04YL-U-S
PUP5C04BU-U-S	PUP5C04BU-F-S
PUP5C04WH-U-S	PUP5C04WH-F-S