HellermannTyton

10/25/2021

Subject: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type (Only Checked Changes Apply)			
□ Production/assembly location		□ Material	⊠ End of Life w/ replacement
☑ Part Number/Ordering Code		Packaging	\Box End of Life w/o replacement
□ Country of Origin		□ Point of Purchase	□ Additional tool/refurbishment
Design (fit, form, function)		Point of Pick up	□ Cost/Lead Time
Engineering record (non-fit, form, function)		□ Supply Chain	\Box Process
Additional Information			
From: To:			
HT Order Code: 133-00993, 133-00994, 133-00996 HT Order Code: 151-03253, 151-03254, 151-03256			
Country of Origin: Mexico		Country of Origin: Mexico	
Manufacturing Location: Mexico		Manufacturing Location: Mexico	
Scope			
HT PN / Ordering Code	Customer PN		Change Effective*
133-00993, 133-00994, 133-00996	1436-2437-ND, 1436-2438-ND,		2/21/2022
	1436-2439-ND		

*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 11/19/2021, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Dylan Goetzke Quality Project Administrator Office: 414 355 1130 x 8751 Email: <u>dylan.goetzke@htamericas.com</u>