

**ABRACON, LLC
ENGINEERING/PROCESS CHANGE NOTIFICATION FORM**

ABRACON ENGINEERING ORIGINATOR:

IMPLEMENTATION DATE: 05/11/2018

NOTIFICATION DATE:

05/11/2018

SCD/DRAWING AFFECTED:

[AB-RTCMC-32.768kHz-EOZ9-S3
DTCXO Temperature Compensated Real
Time Clock Module with I2C Bus](#)

REV: I.R.

NEW REV: A

EFFECTIVITY DATE: 05/11/2018

ECO# 3299

REASON FOR CHANGE:

Part number builder configuration revised to meet new character number limitations.

DETAILS OF SPECIFICATION CHANGE:

APPLICATION INFORMATION

Dashes in Part Number Builder portion removed.

Initial Release (I.R.) Part Numbers (previous)

Dashes in part number builder highlighted in yellow:

1. AB-RTCMC-32.768kHz-EOZ9-S3-D-A
2. AB-RTCMC-32.768kHz-EOZ9-S3-D-A-T
3. AB-RTCMC-32.768kHz-EOZ9-S3-D-B
4. AB-RTCMC-32.768kHz-EOZ9-S3-D-B-T
5. AB-RTCMC-32.768kHz-EOZ9-S3-H-A
6. AB-RTCMC-32.768kHz-EOZ9-S3-H-A-T
7. AB-RTCMC-32.768kHz-EOZ9-S3-H-B
8. AB-RTCMC-32.768kHz-EOZ9-S3-H-B-T

Revision A (Rev. A) Part Numbers (revised)

Dashes in part number builder highlighted in yellow above no longer exist in the part number:

1. AB-RTCMC-32.768kHz-EOZ9-S3-DA
2. AB-RTCMC-32.768kHz-EOZ9-S3-DAT
3. AB-RTCMC-32.768kHz-EOZ9-S3-DB
4. AB-RTCMC-32.768kHz-EOZ9-S3-DBT
5. AB-RTCMC-32.768kHz-EOZ9-S3-HA
6. AB-RTCMC-32.768kHz-EOZ9-S3-HAT
7. AB-RTCMC-32.768kHz-EOZ9-S3-HB
8. AB-RTCMC-32.768kHz-EOZ9-S3-HBT

Safety

Non Safety

Application:

(Check one)

DISPOSITION OF CURRENT STOCK

Scrap

Transfer to: _____

Use as is

Return to vendor

ABRACON INTERNAL APPROVAL:

APPROVAL (PRES) _____ DATE **05/11/2018** _____

GLOBAL QUOTING/PRICING MGR _____ DATE **05/11/2018** _____

ENGINEERING VP _____ DATE **05/11/2018** _____

PURCHASING MGR _____ DATE **05/11/2018** _____

SALES VP _____ DATE **05/11/2018** _____

QUALITY & PROCEESS IMPROVEMENT MGR: _____ DATE **05/11/2018** _____

CUSTOMER APPROVAL (If Applicable)

ENGINEERING: NAME: _____ TITLE: _____ DATE: _____

BUYER/PURCHASING: NAME: _____ TITLE: _____ DATE: _____