

## Product Change Notice

Issue Date: 26-Aug-2021

**Change Description:**

1. Removal of black paint on LED substrate.
2. Change of package marking.

**Parts Affected:**

AUV3-SQ32-ORTOK  
 AUV3-SS32-ORUOK  
 AUV3-ST32-OSVOK  
 AUV3-SQ62-ORTOK  
 AUV3-SS62-ORUOK  
 AUV3-ST62-OSVOK

**Description and Extent of Change:**





1. Removing of black paint on substrate surface.
2. Change from double cathode mark to single cathode mark.

**Reasons for Change:**

Standardization of substrate

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

No change on fit, function, quality and reliability of the final product. Visual changes are illustrated below.

Parameter	Before change	After change
Visual Appearance		
Package drawing		



**Effective Date of Change:**

Shipment with the above changes will commence 30 days after the issuance date above. (Date code: 2140)

**Qualification Data:**

No change in reliability performance. The changes only affect the appearance of the product.

**Software / Firmware Update:**

NA

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.