

# Amphenol Taiwan Corporation

## Product Change Notification

<b>Part Numbers Concerned :</b>	G861ABXXX1TS5HR	<b>Originator:</b>	Sandy Wu
<b>Product Description:</b>	G861 SERIES, WAFER 2.54 PITCH, STRAIGHT PCB MOUNT, W/CAP	<b>Issue Date:</b>	2021/10/15
		<b>PCN NO:</b>	1210-21001207
<b>Distribution:</b>	REMOVE 08-12P, ADD DIM,PLATING OPTION AND SOLDER AREA INFORMATION.		

### Product Change Notice

- This notification is to inform customers that part G861ABXXX1TS5HR for REMOVE 08-12P, ADD DIM,PLATING OPTION AND SOLDER AREA INFORMATION.

### Background:


#### Before

20	48.26	50.80
19	45.72	48.26
18	43.18	45.72
17	40.64	43.18
16	38.10	40.46
15	35.56	38.10
14	33.02	35.56
13	30.48	33.02
12	27.94	30.48
11	25.40	27.94
10	22.86	25.40
09	20.32	22.86
08	17.78	20.32
07	15.24	17.78
06	12.70	15.24
05	10.16	12.70
04	7.62	10.16
03	5.08	7.62
02	2.54	5.08
NO. OF POS.	DIM. A	DIM. B

1

2

# Amphenol Taiwan Corporation Product Change Notification



PART NUMBER:  
G861AB XX X X 1TS5HR


NO. OF POS. ——— CONTACT FINISH:  
1: 100μ" MATTE TIN  
2: GOLD FLASH

COLOR OPTION ———  
1: BLACK  
2: NATURAL

## After

	07	15.24	17.78
	06	12.70	15.24
	05	10.16	12.70
	04	7.62	10.16
F	03	5.08	7.62
	02	2.54	5.08
	NO. OF POS.	DIM. A	DIM. B

# Amphenol Taiwan Corporation Product Change Notification



PART NUMBER:  
G861AB XX X X 1TS5HR

NO. OF POS. —

COLOR OPTION —  
1: BLACK  
2: NATURAL

CONTACT FINISH/SOLDER AREA  
1: 100 $\mu$ m MATTE TIN/100 $\mu$ m MATTE TIN  
2: GOLD FLASH/GOLD FLASH  
3: 15 $\mu$ m GOLD/15 $\mu$ m GOLD  
4: 30 $\mu$ m GOLD/30 $\mu$ m GOLD

## Product Part Number Affected:

G861ABXXXX1TS5HR

## Implementation date:

To be define after customers confirmation.

## Recommended Action:

Sales representative to inform customers for drawing updated.

DOC#:QRF-04-041 A