

1 Products affected

Product hierarchy no. *		Part no.	SBU	Type / Description	Customer part no.		
SBU	PG	PUG	Туре				
02		0.0	0000001143	See list below	Power entry module	GSF2	


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

	List of part numbers affected							
GSF2.0011.01	GSF2.1010.01 GSF2.1011.01	GSF2.1013.01 GSF2.1022.01	GSF2.2010.01					
GSF2.2011.01	GSF2.2013.01 GSF2.2022.01	GSF2.2035.01						

2 Type of change

- Change of approval marks on the product.
- Modified label.

3 Detailed description of change



4 Reason of change

Standards update according to the new UL/CSA 60320-1.

5 Release date

The change will be rolled out starting ww 192019 (Date code 1919 or higher on packaging label) and lasts approx. 6 months depending on the variant. This change has no effect on the validity of the approval certificates.

Product Change Notification						GSF2 Power Entry Module		
owner	creation date	release date	released by	change order no	rev	page	D40 033 006	
sariogar	11.01.2019	25.03.2019	blumhe	2016928	Α	1 of 2	D10-033-006	



6 Impact of change and recommended action

Form Yes Change of approval marks

Fit No Function No Manufacturing No -

Label Yes Change on label

Packaging No -

7 Reference Documents / Attachments

Kind of document	Remarks
GSF2 Data Sheet	

Product Change Notification					GSF2 Power Entry Module		
owner	creation date	release date	released by	change order no	rev	page	D40 033 006
sariogar	11.01.2019	25.03.2019	blumhe	2016928	Α	2 of 2	D10-033-006