

Sensing and Control
1985 Douglas Drive North
Golden Valley, MN 55422
1-815-235-5500

November 24, 2014

< Customer FSE First Name> < Customer FSE Last Name>
< Cust Name>
<Customer Address (1st Line)>
< Customer City>, < Customer State Abbr> < Customer Zipcode>
< Customer Country Desc>

Dear < Customer FSE Last Name>,

Subject: Announcing Obsolescence of Certain Fiber Optic Components

Effective immediately, Honeywell Sensing and Control (S&C) is announcing the obsolescence of certain fiber optic components. The supplier of the LED used in the below products has recently announced the phase out of their product, without the possibility to place a last time buy order.

Affected Listings

Part numbers	Possible replacement	Main difference
GFE1011-5083	none	
GFE1011-5090	none	
HFE1011-001-AAA	none	
HFE1011-001-ABA	none	
HFE1011-012-AAA	none	
HFE1011-5080	none	
HFE1011-590	none	
HFE1011-B	none	
HFE1011-E	none	
HFX6015-200	HFX7000-200	Housing dimensions *
HFX6015-200K	HFX7000-200	Housing dimensions *
HFX6015-210	HFX7000-200	Housing dimensions *

*The HFX7000 housing has threaded M2 holes, about 8mm deep. The HFX6015 didn't have threads, needed self-tapping screws.

Contact Information

For additional information, please contact:

- Product Specialist, Optical and Magnetic Sensor Lines: Nicolas Roche, Nicolas.Roche@honeywell.com, (33) (0) 476 417 212

Best regards,

Nicolas Roche

Nicolas Roche
Product Specialis

