

8755 W. Higgins Road Suite 500 Chicago, IL 60631 www.littelfuse.com

Subject: Notice of Replacement – LPXV Series 1500V Fuse Holder Replaced With LFPXV

Document# LFPCN_PG0093

Date: 01/03/2018

This letter is to inform Littelfuse Sales, Sales Support & Customers that our LPXV Series 1500V holder is being replaced by our new LFPXV Series holder. The LFPXV's improved design has proven to be preferred by most customers in the industry. The new holder also allows Littelfuse to scale up manufacturing output to match demand that has grown dramatically as customers migrate toward the 1500V platform. This surge in demand has quickly depleted available inventory of the LPXV0001Z (old-design holder). Littelfuse will be discontinuing the LPXV Series holder effective immediately and will be offering the LFPXV Series holder as an alternative.

The new LFPXV holder has added features such a single piece hinged design for quick and easy fuse replacement and probe holes for fuse status checks without having to remove the fuse or open the holder. It also has same UL Listed performance as the LPXV holder. For a complete dimensional comparison, please see page 2. Below are the affected ordering part numbers.

| Discontinued Part No. | Replacement Part No. |
|-----------------------|----------------------|
| LPXV0001Z | LFPXV0001Z |

If you have any questions, please contact a Littelfuse representative.

Regards,




Expertise Applied Answers Delivered

Jim McGuire Asssistant Product Manager Industrial Business Unit Littelfuse, Inc. Tel: +1 773-628-0708 Fax: +1 773-830-1797 www.littelfuse.com/industrial



8755 W. Higgins Road Suite 500 Chicago, IL 60631 www.littelfuse.com

LFPXV DIMENSIONS



LPXV DIMENSIONS

