



Product Change Notice

Micron PCN: 30633
 Date: 3/9/2012

Type of Change:	Manufacturing Process Change	
Title of Change:	eUSB e230 Family — Board Routing Change	
Description of Change:	The eUSB board routing has changed in order to accommodate two different connectors: the standard profile connector (legacy) and a new low profile connector option.	
Reason for Change:	Better align industry standards	
Contact Information:	<u>Marketing Contact</u> ADAMO CORSI ACORSI@MICRON.COM Micron Semiconductor Ital	<u>Engineering Contact</u> DAVID TOY DRTOY@MICRON.COM Micron Semiconductor Prds

Product Affected: eUSB e230 Family

Affected Micron Part Numbers	Replacement Part Numbers
MTFDCAE002SAJ-1M1	MTEDCAE002SAJ-1M2
MTFDCAE002SAJ-1M1IT	MTEDCAE002SAJ-1M2IT
MTFDCAE004SAJ-1N1	MTEDCAE004SAJ-1N2
MTFDCAE004SAJ-1N1IT	MTEDCAE004SAJ-1N2IT
MTFDCAE008SAJ-1N1	MTEDCAE008SAJ-1N2
MTFDCAE008SAJ-1N1IT	MTEDCAE008SAJ-1N2IT
MTFDCAE016SAJ-1N1	MTEDCAE016SAJ-1N2
MTFDCAE016SAJ-1N1IT	MTEDCAE016SAJ-1N2IT

Method of Identification: The second numerical character in the suffix of the new part number will be **2**. Please see example below.

Affected Micron Part Numbers	Replacement Part Numbers
MTFDCAE002SAJ-1M1	MTEDCAE002SAJ-1M 2

Micron Sites Affected: All Sites

Product/Data Availability

New board routing:

Sample Availability:* Now
Qual Data Availability: Now
Production Shipments: 01-April-2012

Current board routing:

Last Time Buy: 10-Jun-2012
Last Time Ship: 31-Aug-2012

Qualification Plan:

eUSB product using the new board routing will be qualified according to Company qualification procedure and best practices. Qualification plan will be available upon request.

Note: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change