



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000815I

DATE: 16-Sep-2014

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Lead-Free Conversion	LMX393AKA	MAX9092AKA+T	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX393AUA	MAX9092AUA+	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX393AUA-T	MAX9092AUA+T	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX393HAKA	N/A	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX393HAKA-T	N/A	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX393HAUA	N/A	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	LMX393HAUA-T	N/A	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MX7821KP	N/A	16-Sep-2014	15-Sep-2016	Part is leaded. Request information on lead-free version
Discontinuance	IMSS03C3+	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	LMX393AUA+TG52	MAX9092AUA+T	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX11288EWX+CFJ	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX11288EWX+TCFJ	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX30101EVKIT+	MAX30101EFD+	16-Sep-2014	15-Sep-2016	EVKIT is No Longer Supported
Discontinuance	MAX4230AXK+TG071	MAX4230AXK+T	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX5621UTK+	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX5621UTK+T	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX5631UTK+	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX5631UTK+T	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX6012AEURG05	N/A	16-Sep-2014	15-Sep-2016	Part can no longer be manufactured
Discontinuance	MAX6509CAZK/V+	MAX6509CAUK+	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX6509CAZK/V+T	MAX6509CAUK+T	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX6613MXK/V+	MAX6613MXK+	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX6613MXK/V+T	MAX6613MXK+T	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX7651CCB+	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX7651ECB+	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX7652CCB+	N/A	16-Sep-2014	15-Sep-2016	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 17-Oct-2014

Discontinuance	MAX7652ECB+	N/A	16-Sep-2014	15-Sep-2016	The part was not released
Discontinuance	MAX9024AUD/V+	MAX9024AUD+	16-Sep-2014	15-Sep-2016	The part was not released