



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000791

DATE: 24-Feb-2015

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX7032EVSYS-315	N/A	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX1978ETM	MAX1978ETM+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX8556ETE	MAX8556ETE+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX1993ETG	MAX1993ETG+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX8556ETE-T	MAX8556ETE+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX4766AETA	MAX4766AETA+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX1471EVSYS-315	N/A	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX4890ETJ	MAX4890ETJ+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	806-0713-21	806-0713-21+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX2140ETH-T	MAX2140ETH+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX8557ETE-T	MAX8557ETE+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	806-0713-21-T	806-0713-21+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX1870AETJ-T	MAX1870AETJ+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX3202EETT-T	MAX3202EETT+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX3204EETT	MAX3204EETT+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX16010TAA-T	MAX16010TAA+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX3620DETT	MAX3620DETT+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX3203EETT	MAX3203EETT+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX1870AETJ	MAX1870AETJ+	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX6760TATGD3-T	MAX6760TATGD3+T	27-Aug-2015	24-Feb-2017	Part is leaded, and a lead-free replacement exists

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 27-Mar-2015