

TE Connectivity

Product Change Notification: P-20-018569 PCN Date: 27-JAN-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
MOD2 PIN HEADER 2X5P

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from Outside Vendor in Hungary to Outside Vendor in Tunisia.

Reason for Changes:

Dear Customer, we hereby inform you about a transfer of tools and/or processes to further improve our Supply Chain towards our customers as well as improving our Footprint amendment within TE Connectivity. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The receiving manufacturing locations operates under a certified quality management system in accordance with standard automotive requirements and the respective customer specific requirements. Upon request, a PPAP Level 1 / VDA Level 0 will be available, or as otherwise agreed. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN. For further details please get in touch with your respective Sales or Customer Service Account.

| Estimated Dates: | |
|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 17-FEB-2020 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |

No Mixed Shipments

Part Number(s) being Modified:

| Part Number | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|-------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 969587-1 | NO | | | | | | |

Part Number(s) being Modified:

| | | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|---|----------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| | Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 9 | 969587-1 | NO | | | | | | |

Part Number(s) being Modified:

| | Part Discontinued per | | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|----------|-----------------------|---------|---------------|------------|-----------------|-----------------------|----------------|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 969587-1 | NO | • | | | | | |

Part Number(s) being Modified:

| Part | Part Discontinued per PCN | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|-----------------|---------------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| Number | | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| <u>969587-1</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|----------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 969587-1 | NO | | | | | | |