



OVERVIEW

DATE ISSUED:	June 29, 2020	TRACKING NUMBER:	4134786
ISSUED BY:	AirPrime Product Management		
PRODUCTS AFFECTED:	BX3100, BX3105		
BULLETIN:	Updated Notification of EOL of SKU#1104114 & 1104115		
SKU AFFECTED:	1104114, BX3105, Generic, WiFi, P1.0.1 1104115, BX3100, Generic, WiFi, P1.0.1		
URGENCY:	Urgent		
FOR DISTRIBUTION TO:	All Customers		

Details of Change

DETAILS of CHANGE	Due to availability of newer FW versions with various bug fixes, Customer should immediately move to SKUs with newer FW versions (WiFi 2.7.2 updated)
EFFECTIVE DATE:	LTB (Last Buy time) date for SKUs 1104114 & 1104115 is September 30th, 2020 LTS (Last Time Shipment) date for SKUs 1104114 & 1104115 is December 12th, 2020 . All shipments must complete on or before this date.
Replacement SKUs	1104662, BX3105, Generic, WiFi, 2.7.2 1104528, BX3105, Generic, WiFi, 2.6.3 1104231 BX3105, Generic, WiFi, 2.5.0 1104660, BX3100, Generic, WiFi, 2.7.2 1104529, BX3100, Generic, WiFi, 2.6.3 1104230, BX3100, Generic, WiFi, 2.5.0
For further information, please contact	Your Sierra Wireless sales/technical support contact