

TE Connectivity

Product Change Notification: P-19-017872

PCN Date: 05-SEP-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description: 2x2 PLUG ASSY

Description of Changes

Dear customer, we would like to inform you about the upcoming front of a new tool to replace the old one. (Mold # 21-487709)

| Reason for Changes: | | | | | | |
|--|--|--|--|--|--|--|
| Product improvement.Current Tool Life Cycle been reached | | | | | | |
| Estimated Dates: | | | | | | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | | | |
| | 09-MAR-2020 | | | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | | | |
| | No Mixed Shipments | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u>184244-1</u> | NO | | | | | | |
| <u>184248-1</u> | NO | | | | | | |
| 184344-1 | NO | | | | | | |
| <u>184349-1</u> | NO | | | | | | |
| <u>184392-1</u> | NO | | | | | | |
| <u>184393-2</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 184344-1 | NO | Brannig | | itumber(0) | | indiniber(6) | Difference |
| 184349-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u>184344-1</u> | NO | | | | | | |
| <u>184349-1</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part | Part Discontinued per | Customer | Customer Part | Alias Part | Substitute Part | Substitute Alias Part | Description Of |
|-----------------|-----------------------|----------|---------------|------------|-----------------|-----------------------|----------------|
| Number | PCN | Drawing | Number | Number(s) | Number | Number(s) | Difference |
| 184244-1 | NO | | | | | | |
| <u>184248-1</u> | NO | | | | | | |
| <u>184392-1</u> | NO | | | | | | |
| <u>184393-2</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 184244-1 | NO | | | | | | |
| <u>184248-1</u> | NO | | | | | | |
| <u>184392-1</u> | NO | | | | | | |
| <u>184393-2</u> | NO | | | | | | |