

PRODUCT CHANGE NOTIFICATION

Product Category SAFETY - PTD 20200316

Product Group ID SAFETY AND ACCESSORIES

ISSUE DATE: 20200316

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The Panduit VeriSafe Split Bolt Connection Kits and Split Bolt VeriSafe Retrofit Kits will be discontinued, due to extremely low demand. The split bolts will be able to be purchased individually, if required.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2020	7	6

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Type	Replacement Part 1	Replacement Part 2
VS-CKBB2-00	Direct Replacement	VS-CKP4-000	
VS-CKBB6-2	Multiple Replacements	VS-CKP4-000	VS-CKP14-6
VS-CKBB8-4	Direct Replacement	VS-CKP14-6	
VS-CKSB1-00	Direct Replacement	VS-CKP4-000	
VS-CKSB10-8	Direct Replacement	VS-CKP14-6	
VS-CKSB6-2	Multiple Replacements	VS-CKP4-000	VS-CKP14-6
VS-AVT-RKBB2	Direct Replacement	VS-AVT-C08-L10	
VS-AVT-RKBB3	Direct Replacement	VS-AVT-C08-L10	
VS-AVT-RKBB4	Direct Replacement	VS-AVT-C08-L10	
VS-AVT-RKSB1	Direct Replacement	VS-AVT-C08-L10	
VS-AVT-RKSB2	Direct Replacement	VS-AVT-C08-L10	
VS-AVT-RKSB3	Direct Replacement	VS-AVT-C08-L10	