

ABRACON, LLC ENGINEERING/PROCESS CHANGE NOTIFICATION FORM			
ABRACON ORIGINATOR:	IMPLEMENTATION DATE:02/03/2017 SCD/DRAWING AFFECTED:		
NOTIFICATION DATE:	APAM1348YD13V2.0  GPS Patch Antenna  REV: Initial		
02/03/2017	NEW REV: A		
	EFFECTIVITY DATE: 02/03/2017		
	ECO# 3149		
REASON FOR CHANGE: Discontinued – Declining Sales/Obsolete, Effective immediately. No last time buy notification from factory			
DETAILS OF SPECIFICATION CHANGE:	APPLICATION INFORMATION		
EOL by factory since Sept. 2016	Safety	Non Safety	Application:
Factory has provided an Alternative solution APAM1368YB13V3.0 Factory states there is no difference on performance between the two, however a close look between data sheets, the alternative is not a direct drop in replacement. Height difference (6.7mm) vs. (5.6mm), and other electrical differences, i.e. Gain, LNA VSWR, Centre Frequency, & LNA Gain.  PLEASE REFER to DATA SHEETS.	(Check one)		
		0	•
	□ Scrap		STOCK
ABRACON INTERNAL APPROVAL:			
President CEODATE 02/03/201			
GLOBAL QUOTING/PRICING MGDATE 02/03/20	<u></u>		
ENGINEERING VP DATE 02	/03/2017		
PURCHASING MGR DATE 02	2/03/2017		
SALES VPDATE 02	<u>//03/20</u> 17		
QUALITY & PROCEESS IMPROVEMENT MGR_DATE 02/03/2017			