transphorm

805-456-1300

Product Information Letter

Dear Distributor,

Transphorm's product marketing team wishes to advise you that the products listed below are now classified as "Not Recommended for New Designs." This is a continued activity of our product consolidation program. The products listed here will remain available to existing customers only. <u>Orders for the below products will not be accepted from new customers so please list them as not recommended for new designs without replacement.</u>

End-of-Life Products with Recommended Replacement Parts	
Not Recommended for New Designs	Replacement Part
TPH3206LSB	Not available
TPH3206LDGB	Not available
TPH3208LDG	Not available
TPH3208LSG	Not available
TPH3205WSB	TP65H050WS
TPH3207WS	TP65H035WS

These products will be defocused on Transphorm's website by the end of May 2018. Their datasheets will still be available if searched for in the website's search engine. There will be no replacement parts offered for these devices as we realign Transphorm's product line to primarily include 35, 50, 70, 110 and 150m Ω devices in TO-220 and TO-247 packages with only the Gen III 70m Ω being offered in the PQFN88 package that will be qualified later this year.

If you have any questions, please let me know

Regards, Philip Zuk Vice President, Technical Marketing