

TE Connectivity

Product Change Notification: E-20-008880 PCN Date: 24-JUN-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Force Guided Relay SR4 & SR6 second source for contact rivets

Description of Changes

The following part numbers contain contact rivets, for which TE has approved an additional supplier (second source). The contacts from the additional supplier are identical in form and dimensions, in their material, manufacturing process as well as their specification. The product specifications of SR4 and SR6 relays remain unchanged. --- [You may have already received the original notification (E-20-007708), which unfortunately did not contain all affected part numbers. This additional notification covers the missing part numbers.]

Reason for Changes:

Manufacturing / Process Requirements. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to deliver our products on time, we've made the decision to approve an additional contact rivet supplier as a second source. This allows us to maintain production in case of a drop-out of our primary supplier.

Estimated Dates:

Stimated Dates.					
Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):					
	19-AUG-2020				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	No Mixed Shipments				

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
3-1415042-1	NO			"SR6ZC024"			
5-1415033-1	NO			"SR6ZB024"			

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number		Number	Number(s)	Difference
1393260-7 NO	NO			"V23050-A1024-A542",			
	NO			"V23050A1024A542"			
1415015-1	110			"V23050-A1024-A533",			
	NO			"V23050A1024A533"			
3-1415042-1	NO			"SR6ZC024"			
5-1415033-1	NO			"SR6ZB024"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393260-7	NO	Diaming	- rumber		- Humber	rum ser(s)	Difference

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"V23050-A1024-A542",			
				"V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533",			
	NO			"V23050A1024A533"			
3-1415042-1	NO			"SR6ZC024"			•
5-1415033-1	NO			"SR6ZB024"			