

Global Change Notification (GCN)

Product Family	EVC JACKSCREW WITH CAP	10630895
		GCN Number
Series	71757	March 26, 2014
		Date Issued
Reason For Change	Obsolescence	
Change Description	Obsolete below P/N due to no long tool and suppliers support. LTB date is 2014/8/29; LTS date is 2015/2/27. Part is obsolete with 71757-1001 replacement.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Not Applicable	
Assessment Of Change (How Product Will Be Qualified & Validated)	N/A	
Internal Molex Qualification Date (Planned Date Information Available)		
Sample Availability Date (Changed Part)		
Date of Implementation	February 27, 2015	
Method of Identifying Change	N/A	
Recommended Replacement Parts	717571001	
Last Time Buy Date for Obsolete Parts	August 29, 2014	
Last Time Ship Date for Obsolete Parts	February 27, 2015	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com