

Product Change Notification

TE Connectivity

Product Change Notification: E-18-002954 PCN Date: 19-MAR-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Deutsch AEC/DRC/DT/DTP/DTM/DRCP Series flange seal, interface seal, grommet supplier manufacturing location change.

Description of Changes

The Industrial and Commercial Transportation (ICT) business unit of TE Connectivity (TEC) intends to move the molding of the flange seals, interface seals and wire grommet that is used in the part number(s) listed below from the current supplier located in Northern part of USA to southern part of USA. We hereby reserve the right to move the tool back to the current location of the supplier as business needs require this. Final assembly of the connectors will remain in ICT-Tullahoma, Tennessee campus. This PCN is in effect immediately and indefinitely.

| Reason for Changes: | | | | | | | | |
|---|--|--|--|--|--|--|--|--|
| Dear Customer, we inform you of this move as part of our aggressive continuous improvement efforts and to meet on time product shipments. An internal release based on our specifications will be executed before any parts are delivered. Level 3 PPAP packages by part number assembly will be offered upon customer request. | | | | | | | | |
| Estimated Dates: | Estimated Dates: | | | | | | | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | | | | | |
| | 23-MAR-2018 | | | | | | | |
| ast Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only): | | | | | | | | |
| | 22-MAR-2021 | | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|---------------------------|---------------------|-------------------------|----------------------|---------------------------|------------------------------------|------------------------------|
| DRC13-40PA | NO | | | "ZPF000000000131279 | | | |
| DRC22-50P01 | NO | | | "ZPF000000000131361 | • | | |
| DT13-12PA | NO | | | | | | |
| DT13-12PA- B016 | NO | | | | | | |
| DT13-4P | NO | | | | | | |
| DT13-6P | NO | | | | | | |
| DT15-12PA | NO | | | | | | |
| DT15-12PA- B016 | NO | | | | | | |
| DT15-12PB | NO | | | | | | |
| DT15-12PD | NO | | | | | | |
| DT15-4P | NO | | | | | | |
| DT15-6P | NO | | | | | | |
| DTM13-12PA | NO | | | "ZPF000000000130584 | - | | |
| DTM15-12PA | NO | | | "ZPF000000000130591 | • | | |
| DTM15-12PC | NO | | | "ZPF000000000130593 | • | | |
| DTP10-4P | NO | | | "ZPF000000000130282 | | | · |
| DTP13-4P | NO | | | | | | · |
| DTP15-4P | NO | | | | | | |

Part Number(s) being Modified:

| | (-)3 | | | | | | |
|-----------|-------------------|----------|---------------|----------------------|-----------------|-----------------------|----------------|
| Part | Part Discontinued | Customer | Customer Part | Alias Part Number(s) | Substitute Part | Substitute Alias Part | Description Of |
| Number | per PCN | Drawing | Number | Alias Part Number(s) | Number | Number(s) | Difference |
| DT13-12P/ | A NO | | | | | | |
| DT13-4P | NO | | | | | | |
| | | | | | | | |

| Part | Part Discontinued | Customer | Customer Part | Alias Part Number(s) | Substitute Part | Substitute Alias Part | Description Of |
|-------------------------------|-------------------|----------|---------------|-----------------------|-----------------|-----------------------|----------------|
| Number | per PCN | Drawing | Number | Alias Fartivariber(s) | Number | Number(s) | Difference |
| DT13-6P | NO | | | | | | |
| DT15-12P | NO NO | | | | | | |
| DT15-12PI | 3 NO | | | | | | |
| DT15-12PI | ON C | | | | | | |
| DT15-4P | NO | | | | | | |
| DT15-6P | NO | | | | | | |
| DTM13- | NO | | | "ZPF000000000130584" | | | |
| <u>12PA</u> | 110 | | | 21 1 000000000 100004 | | | |
| DTM15- | NO | | | "ZPF000000000130591 | " | | |
| <u>12PA</u> | | | | | | | |
| <u>DTM15</u> - <u>12PC</u> | NO | | | "ZPF000000000130593 | 8" | | |

Part Number(s) being Modified:

| Part | Part Discontinued | Customer | Customer Part | | Substitute Part | Substitute Alias Part | Description Of |
|-------------------------------|-------------------|----------|---------------|----------------------|-----------------|-----------------------|----------------|
| Number | per PCN | Drawing | Number | Alias Part Number(s) | Number | Number(s) | Difference |
| DT13-12P/ | NO A | | | | | | |
| DT13-4P | NO | | | | | | |
| DT13-6P | NO | | | | | | |
| DT15-12P/ | A NO | | | | | | |
| DT15-12PI | NO NO | | | | | | |
| DT15-12PI | O NO | | | | | | |
| DT15-4P | NO | | | | | | |
| DT15-6P | NO | | | | | | |
| <u>DTM13</u> - <u>12PA</u> | NO | | | "ZPF000000000130584 | ļ" | | |
| <u>DTM15</u> - 12PA | NO | | | "ZPF000000000130591 | " | | |
| DTM15- 12PC | NO | | | "ZPF000000000130593 | 3" | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|---------------------|-------------------------|----------------------|---------------------------|------------------------------------|------------------------------|
| DRC13-40P | | | | "ZPF000000000131279 | " | . , | |
| DRC22- 50P01 | NO | | | "ZPF000000000131361 | " | | |
| DT13-12PA | NO | | | | | | |
| <u>DT13-12PA</u> - B016 | NO | | | | | | |
| DT13-4P | NO | | | | | | |
| DT13-6P | NO | | | | | | |
| DT15-12PA | NO | | | | | | |
| DT15-12PA- B016 | NO | | | | | | |
| DT15-4P | NO | | | | | | |
| DT15-6P | NO | | | | | | |
| DTM13-12PA | NO | | | "ZPF000000000130584" | 1 | | |
| DTM15-12PA | NO | | | "ZPF000000000130591" | 1 | | • |
| DTP10-4P | NO | | | "ZPF000000000130282" | 1 | | |
| DTP13-4P | NO | | | | | | |
| DTP15-4P | NO | | | | | | _ |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------|---------------------------|---------------------|-------------------------|----------------------|---------------------------|------------------------------------|------------------------------|
| DRC13-40PA | NO | | | "ZPF000000000131279" | | | |
| DRC22- 50P01 | NO | | | "ZPF000000000131361 | II | | |
| DT13-12PA | NO | | | | | | |
| DT13-12PA- B016 | NO | | | | | | |
| DT13-4P | NO | | | | | | |
| DT13-6P | NO | | | | | | |
| DT15-12PA | NO | | | | | | |
| DT15-12PA- B016 | NO | | | | | | |
| DT15-4P | NO | | | | | | |
| DT15-6P | NO | | | | | | |
| DTM13-12PA | NO | | | "ZPF000000000130584" | 1 | | |
| DTM15-12PA | NO | | | "ZPF000000000130591" | • | | |
| DTP10-4P | NO | | | "ZPF000000000130282" | | | |
| DTP13-4P | NO | | | | | | |
| DTP15-4P | NO | | | | | | |