

## MICRON\_General Firmware Maintenance Release 954300T0 and 95420280 for Micron 7300 SSDs

PCN: 34557

Published: 2022-01-26

MTFDHBE1T6TDG-1AW42ABYY

Туре:	Firmware Revision, Product Mark/label Change			
Description:	7300 954300T0 firmware replaces 954300P0 firmware for Security Enabled Devices (SED) and 95420280 firmware replaces 95420260 / 95420100 firmware. Firmware 954300T0 and 95420280 contain the following improvements:			
	-Feature & performance enhancements			
	-LED status and activity upgrades			
	-System stability improvements			
	-General error and protocol improvements			
	-Asynchronous power-loss improvements			
	-Asynchronous power-ioss improvements			
	Note: Label text will also be updated beginning w	th FW release. Please see attached document.		
Anticipated Impact:	No form, fit, function change.			
Reason:	Better Align With Industry Standard, Improved Product Quality and Reliability			
Product Affected:	All 7300 part numbers			
Affected Micron Part Number	Recommended Replacement	Customer Part Number		
MODULE				
MTFDHBA400TDG-1AW12ABYY				
MTFDHBA400TDG-1AW1ZABY		557-MTFDHBA400TDG-1AW1ZABYY-NI		
MTFDHBA400TDG-1AW42ABYY				
MTFDHBA400TDG-1AW4ZABY	Y	557-MTFDHBA400TDG-1AW4ZABYY-NI		
MTFDHBA400TDG-2AW1ZABYY				
MTFDHBA480TDF-1AW12ABYY				
MTFDHBA480TDF-1AW1ZABYY	Y	557-MTFDHBA480TDF-1AW1ZABYY-ND		
MTFDHBA480TDF-1AW42ABYY				
MTFDHBA480TDF-1AW4ZABYY	Y	557-MTFDHBA480TDF-1AW4ZABYY-ND		
MTFDHBA480TDF-2AW1ZABYY				
MTFDHBA800TDG-1AW12ABYY				
MTFDHBA800TDG-1AW1ZABY	Y	557-MTFDHBA800TDG-1AW1ZABYY-NI		
MTFDHBA800TDG-1AW42ABYY				
MTFDHBA800TDG-1AW4ZABYY	Y	557-MTFDHBA800TDG-1AW4ZABYY-ND		
MTFDHBA800TDG-2AW1ZABYY				
MTFDHBA960TDF-1AW12ABYY				
MTFDHBA960TDF-1AW1ZABYY	Y	557-MTFDHBA960TDF-1AW1ZABYY-ND		
MTFDHBA960TDF-1AW42ABYY				
MTFDHBA960TDF-1AW4ZABYY	Y	557-MTFDHBA960TDF-1AW4ZABYY-ND		
MTFDHBA960TDF-2AW1ZABYY				
MTFDHBE1T6TDG-1AW12ABYY				

MTFDHBE1T6TDG-1AW4ZAB	vv		557-MTFDHBE1T6TDG-1AW4ZABYY-ND
MTFDHBE1T9TDF-1AW12ABYY			
MTFDHBE1T9TDF-1AW1BABY			
MTFDHBE1T9TDF-1AW1ZABY	-		557-MTFDHBE1T9TDF-1AW1ZABYY-ND
MTFDHBE1T9TDF-1AW42ABYY			
MTFDHBE1T9TDF-1AW4ZABY			557-MTFDHBE1T9TDF-1AW4ZABYY-ND
MTFDHBE3T2TDG-1AW12ABY	Y		207 10000 2000 200 2000 1000 1000 2000 2
MTFDHBE3T2TDG-1AW1ZAB	YY		557-MTFDHBE3T2TDG-1AW1ZABYY-ND
MTFDHBE3T2TDG-1AW42ABY	Y		
MTFDHBE3T2TDG-1AW4ZAB	YY		557-MTFDHBE3T2TDG-1AW4ZABYY-ND
MTFDHBE3T8TDF-1AW12ABYY	Y		
MTFDHBE3T8TDF-1AW1BABY	Y		
MTFDHBE3T8TDF-1AW1ZABY	YY		557-MTFDHBE3T8TDF-1AW1ZABYY-ND
MTFDHBE3T8TDF-1AW42ABYY	Y		
MTFDHBE3T8TDF-1AW4ZABY	YY		557-MTFDHBE3T8TDF-1AW4ZABYY-ND
MTFDHBE6T4TDG-1AW12ABY	Y		
MTFDHBE6T4TDG-1AW1ZAB	YY		557-MTFDHBE6T4TDG-1AW1ZABYY-ND
MTFDHBE6T4TDG-1AW42ABY	Y		
MTFDHBE6T4TDG-1AW4ZAB	YY		557-MTFDHBE6T4TDG-1AW4ZABYY-ND
MTFDHBE7T6TDF-1AW12ABYY	Y		
MTFDHBE7T6TDF-1AW1BABY	Y		
MTFDHBE7T6TDF-1AW1ZABY	YY		557-MTFDHBE7T6TDF-1AW1ZABYY-ND
MTFDHBE7T6TDF-1AW42ABYY	Y		
MTFDHBE7T6TDF-1AW4ZABY	YY		557-MTFDHBE7T6TDF-1AW4ZABYY-ND
MTFDHBE800TDG-1AW12ABY	Y		
MTFDHBE800TDG-1AW1ZABY	YY		557-MTFDHBE800TDG-1AW1ZABYY-ND
MTFDHBE800TDG-1AW42ABYY	Y		
MTFDHBE800TDG-1AW4ZABY	YY		557-MTFDHBE800TDG-1AW4ZABYY-ND
MTFDHBE960TDF-1AW12ABYY	<i>T</i>		
MTFDHBE960TDF-1AW1BABYY	Y		
MTFDHBE960TDF-1AW1ZABY	<b>YY</b>		557-MTFDHBE960TDF-1AW1ZABYY-ND
MTFDHBE960TDF-1AW42ABYY	<i>I</i>		
MTFDHBE960TDF-1AW4ZABY	Y		557-MTFDHBE960TDF-1AW4ZABYY-ND
MTFDHBG1T9TDF-1AW12ABY	Y		
MTFDHBG1T9TDF-1AW1ZAB	YY		557-MTFDHBG1T9TDF-1AW1ZABYY-ND
MTFDHBG1T9TDF-1AW42ABY	Y		
MTFDHBG1T9TDF-1AW4ZAB	YY		557-MTFDHBG1T9TDF-1AW4ZABYY-ND
MTFDHBG1T9TDF-2AW1ZABY	Y		
MTFDHBG3T8TDF-1AW12ABY	Y		
MTFDHBG3T8TDF-1AW1ZAB	YY		557-MTFDHBG3T8TDF-1AW1ZABYY-ND
MTFDHBG3T8TDF-1AW42ABY			
MTFDHBG3T8TDF-1AW4ZAB			557-MTFDHBG3T8TDF-1AW4ZABYY-ND
MTFDHBG3T8TDF-2AW1ZABY	Y		
		*Materials that have been ordered are in <b>bold</b> .	
		material and national and material	
Method of Identification:	Product Label		
Micron Sites Affected:	MSB - Singapore		
Sample Available:	2022-01-26		
Product Ship Date:	2022-02-25		

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

## Attachments