| September 30, 2022         | PCN Number :   | 512690  |
|----------------------------|--|---|
| Packaging Method/Quantit   | y Changing   |   |
|                            |  |   |
| Corrective Actions         |  |   |
| No change to parts - Form/ | Fit/Function   |   |
| November 01, 2022          |  |   |
| October 28, 2022           |  |   |
| October 28, 2022           |  |   |
| mer: September 29, 2022    |  |   |
|                            | This notification is to inform<br>Delivery unit. No changes v<br>Corrective Actions<br>No change to parts - Form/<br>November 01, 2022<br>October 28, 2022<br>October 28, 2022 | No change to parts - Form/Fit/Function<br>November 01, 2022<br>October 28, 2022<br>October 28, 2022 |

 Change of packaging delivery unit and standard quantity needed regarding Molex terminal block part number 395326005



After Picture

## Overview

 To align the delivery unit quantities in our system, Molex is updating the delivery units for the product identified in this change.

- Product Impact
  - No impact to form, fit or function of the products in question.
- Part Number Impact
  - 395326005

## RELEASED

You may address inquires regarding this PCN by clicking on the below link <u>mailto:pcn\_coordinator@molex.com?subject=PCN\_Notification:512690</u> or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : PCN Notification: 512690 " in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com