

TE Connectivity

Product Change Notification: E-18-018587 PCN Date: 04-DEC-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Flat Sensor 2.8mm 5P(936062), Flat Sensor 2.8mm 6P (936394), JPT 3P(368161), JPT 4P(368162)

Description of Changes

Material Change[Zytel FE8018(Dupont) to Technyl R71713(Solvay)]

Reason for Changes:					
Manufacturing / Process Requirements. Material change due to unstable in supply of existing raw material.					
Estimated Dates:					
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	30-APR-2019				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	28-JUN-2019				

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>368161-1</u>	NO						
368162-1	NO						
936394-2	NO						

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>368161-1</u>	NO						
368162-1	NO						
936394-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
368161-1	NO						
368162-1	NO						_
936394-2	NO						