


# Product Obsolescence Memo

## SPARCTUBE® SWITCHING SPARK GAP DEVICES



January 28, 2019

## Bourns® ST Series Sparctube® Switching Spark Gap Devices to be Discontinued

In accordance with our ongoing product lifecycle management procedure, Bourns is discontinuing the ST Series Sparctube® products. A lack of sales volume and diminishing demand necessitates this action. Regrettably, there will be no available substitute or replacement parts for this series of products.

Last time buy opportunities will be limited to stock on hand. Any last time buy purchases will be non-cancellable and non-refundable. Please contact [Bourns Customer Service/Inside Sales](#) for product availability.

Obsolete Product Series				
<a href="#">ST-0350-BXX-STD</a>	<a href="#">ST-0470-BXX-STD</a>	<a href="#">ST-0620-BXX-STD</a>	<a href="#">ST-0800-BXX-STD</a>	<a href="#">ST-1000-AXX-SG</a>
<a href="#">ST-0400-BXX-STD</a>	<a href="#">ST-0600-BXX-STD</a>	<a href="#">ST-0750-BXX-STD</a>	<a href="#">ST-0840-BXX-STD</a>	

Obsolete Part Numbers					
ST-0350-BBT-STD	ST-0470-BLB-STD	ST-0620-BLT-STD	ST-0800-BBT-STD	ST-0800-BLB-STD	ST-0840-BCT-0
ST-0350-BLB-STD	ST-0470-BLT-STD	ST-0750-BBT-STD	ST-0800-BCB-0	ST-0800-BLT-STD	ST-0840-BCT-STD
ST-0350-BLT-STD	ST-0600-BLB-STD	ST-0750-BLB-STD	ST-0800-BCB-STD	ST-0840-BBB-STD	ST-0840-BLB-STD
ST-0400-BLB-STD	ST-0600-BLT-STD	ST-0750-BLT-STD	ST-0800-BCT-0	ST-0840-BBT-STD	ST-0840-BLT-STD
ST-0400-BLT-STD	ST-0620-BLB-STD	ST-0800-BBB-STD	ST-0800-BCT-STD	ST-0840-BCB-0	ST-1000-ALT-SG

Please plan for the following deadlines:

Last time buy date: **March 1, 2019**

Last time ship date: **April 1, 2019**

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

GDT1901