

Global Change Notification (GCN)

Product Family	Magnetic Jacks	10640053
		GCN Number
Series	85718	May 12, 2014
		Date Issued
Reason For Change	Change Construction Or Material	
Change Description	The reason of the change is to aid interoperability by addition of a protection diode per port to PoE circuitry. Molex only adds the protection diode in the upper side (Top PCB - new revision) (and no other form/fit/function involved).	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Special Request	
Assessment Of Change (How Product Will Be Qualified & Validated)	No impact for form, fit and function. Passed functional test. Report is available on request.	
Internal Molex Qualification Date (Planned Date Information Available)	April 07, 2014	
Sample Availability Date (Changed Part)	April 14, 2014	
Date of Implementation	May 30, 2014	
Method of Identifying Change	cutoff date code is labeled on the outer Box lable	
Recommended Replacement Parts	N/A	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com