

Product Change Notification

PCN #: LA5000_202208 Date: August 1, 2022

Part Numbers impacted: Laird Thermal Systems Customer

387005598 N/A

Description of change:

A revision to 387005598 (LA5000) has been made to replace liquid fittings in the unit. The change does not affect form, fit, or function of the system. However, a new part number is being assigned to the LA5000 model to better track the change. The new part number is 387009381.

All open orders should be changed to reflect the new part number.

Information on possible alternative products:

387009381 is the replacement part number for 387005598.

Implementation of change: August 1, 2022

Laird Thermal Systems contact:

<u>Customer Service</u> <u>Product Director</u>

Name: Kady Tkach Greg Ducharme

Email: Kady.Tkach@lairdthermal.com Greg.Ducharme@lairdthermal.com

Laird Thermal Systems will assume this change is accepted unless specific conditions of acceptance are provided in writing within 30 days from the data of this notice. All correspondence must be sent to the contact e-mail addresses listed above.

Web: www.lairdthermal.com