

PRODUCT DISCONTINUATION



PD_016_07

Reason: Dear Customer BFP 540F E6327 is going to be replaced with brand new ESD hardened BFP 540FESD E6327. As well the RF Performance as the package and pinning are unchanged. The ESD performance of BFP 540FESD E6327 is 1kV (HBM) and approx. 5 times better then BFP 540F E6327. For more detail pls. refer to the datasheet.

DISCONTINUED				NEW (REPLACEMENT)			
Device	Ordering Code	Function	Package	Device	Ordering Code	Function	Package
BFP 540F E6327	SP000012988	RF-SIEGET	P/PG-TSFP-4	BFP 540FESD E6327	SP000296093	RF-SIEGET	P/PG-TSFP-4

Last order:	31. August 2007
Last delivery:	29. February 2008