



Product Change Notification (PCN)

PCN Number	510447	Date Issued	September 22, 2021
Reason for Change	Equipment Transfer, Production Transfer or Rearrangement		
Change Type Description	This letter is to inform you that production of the part(s) identified in this notice is being moved to a different production location. No changes will be made to the product as a result of this move.		
Reason for Short Notice	New Capacity		
Assessment of Change	First article inspection		
Internal Molex Qualification Date	October 15, 2021		
Sample Availability Date (Changed Part)	October 15, 2021		
Planned Implementation Date	November 19, 2021		
Method of Identifying Change	Date code		

Before Change

Overview

Insufficient capacity for 5041910199 & 5041920199 terminal and to secure the supply for this terminal in Molex Malaysia.

After Change

Overview

- The purpose of this letter is to add additional manufacturing location for 5041910199 & 5041920199 terminal. The reason for the change is to secure the supply for 5041910199 & 5041920199 due to capacity constraint at Molex Malaysia.
- Molex Malaysia Part Number(s) Affected: 5041910199 & 5041920199
- Product Impact
 - There is no impact of the change since there is no change in design, process on the mold, therefore no change in the Molex assembly part number will occur either.
- Qualification Reports and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510447**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
510447	5041891670
510447	5041892070
510447	5041894070