

研華股份有限公司 Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號 No.1, Alley 20, Lane 26, Rueiguang Road Neihu, District, Taipei, Taiwan 114, R.O.C. Tel: 886-2-2792-7818 Fax: 886-2-2794-7301 www.advantech.com

IIoT Product Change Notice

The change will be applied on the ULI-224TC (BB-485LDRC9). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

Note: The ordering process has not been changed. Customers should continue to order model number BB-485LDRC9.

1. Reason for the Change: Branding & UL File number changing from E222870 to E327848.

2. Affected Products: ULI-224TC (BB-485LDRC9)

3. Impact on Application: No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	No
Physical Outlook Change	Yes
Ordering P/N Change	No
Cut-in Implement	Component Running Change

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-224TC BB-485LDRC9	20BB250- 10727-00	1990034358T010	Label	Old name plate Optically Isolated RS-232 to RS422/485 Converter Model 485LDRC9 RS-232 RS-422/485 (D) TD (G) TD A(-) (D) = Off) (A) RD (K) RD A(-) 7) 4800 Baud 7) 4800 Baud 7) 4800 Baud 8) 9000 Ba	Branding



研華股份有限公司 Advantech Co., Ltd.

台北市內湖區瑞光路26巷20弄1號 No.1, Alley 20, Lane 26, Ruelguang Road Neihu, District, Taipei, Taiwan 114, R.O.C. Tel: 886-2-2792-7818 Fax: 886-2-2794-7301 www.advantech.com

ULI-224TC BB-485LDRC9	20BB9495	1990034427T010	Label	Old name plate This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. CTUSE US E222870 New name plate This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. CTUSE US E327848	UL File Number and Compliance information
--------------------------	----------	----------------	-------	--	---

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM	Estimated	Cut-in	Change
	Number	Effective Date	Implement	Description
ULI-224TC (BB-485LDRC9)	ECOM-193541	11/7/2022	Running Change	Update name plate.

^{*}Note: Cut-in progress depends on factory production schedule.

Contact Windows

PM	Brian Foster / <u>brian.foster@advantech.com</u>
AE	N/A

^{**} Note: The ordering process has not been changed. Customers should continue to order model number BB-485LDRC9