



Product Discontinuation

PDN-IFC-118-2016

| Business Unit | Product Line Code | Type of Change | Action | Date of Issue |
|-------------------------------------|-------------------|-------------------------|-------------------------------|---------------|
| IFC - Industrial Field Connectivity | BF7 | Product Discontinuation | Notify Distributors and Field | 12/14/2016 |

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

The HEAVYCON HC-A, HC-D and HC-Q inserts have been improved and expanded. The new product range offers significant improvements in assembly/installation, cost and shortened lead times.

Stock Status

| | |
|-----------------------------------|-----|
| Can existing stock still be used? | Yes |
| Is mixture of stock acceptable? | No |

Transaction Dates

| | |
|---|-----------|
| Last Buy from Phoenix Contact: | 4/30/2017 |
| Last Scheduled Ship from Phoenix Contact: | 7/31/2017 |



Product Discontinuation





Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation



Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Steven Obert
sobert@phoenixcon.com

Thank you,

Loreen Katz

Product Marketing Manager ICT Field



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Discontinuation

| Discontinued Part # | Type Description | Replacement Part # | Type Description |
|---------------------|------------------|--------------------|---------------------|
| 1408575 | HC-D 7-ESTC-COD | 1418624 | HC-Q07-I-CT-M |
| 1408588 | HC-D 7-EBUC-COD | 1418623 | HC-Q07-I-CT-F |
| 1409419 | HC-Q 12-I-CT-F | 1418625 | HC-Q12-I-CT-F |
| 1409422 | HC-Q 12-I-CT-M | 1418626 | HC-Q12-I-CT-M |
| 1773051 | HC-A 10-ESTS | 1585294 | HC-A10-I-UT-M |
| 1585186 | HC-A 10-ESTS-AU | | |
| 1677005 | HC-A 16-EBUS | 1585320 | HC-A16-I-UT-F |
| 1773080 | HC-A 3-ESTS | 1585210 | HC-A03-I-UT-M |
| 1773093 | HC-A 3-EBUS | 1585223 | HC-A03-I-UT-F |
| 1677021 | HC-A 16-ESTS | 1585317 | HC-A16-I-UT-M |
| 1772492 | HC-D 40-EBUC | 1584428 | HC-D 40-I-CT-F |
| 1773077 | HC-A 10-EBUS | 1585304 | HC-A10-I-UT-F |
| 1677047 | HC-A 16-EBUS-32 | 1585346 | HC-A16-I-UT-F 17-32 |
| 1774908 | HC-A 4-EBUS | 1585249 | HC-A04-I-UT-F |
| 1774911 | HC-A 4-ESTS | 1585236 | HC-A04-I-UT-M |
| 1677063 | HC-A 16-ESTS-32 | 1585333 | HC-A16-I-UT-M 17-32 |