

TE Connectivity

Product Change Notification: E-19-007593 PCN Date: 29-MAY-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DEUTSCH CE Series Panel Nuts and HDC34 protective covers component supplier change

Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is transferring component(s) of the following part number(s) from San Fernando, CA, USA to Queretaro, Queretaro, Mexico. These PNs are TE proprietary designs, therefore considered catalog/general market product. TE reserves the right to move tool back to prior location/supplier based on business need. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:

Dear Customer, we hereby inform you of this change. This change is necessary to meet on time product shipments. The change will not impact connector performance.
IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can
remain stocked until use. Shipments of both configurations may be mixed.

Estimated Dates:

Estimated Dates.				
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):			
	24-JUL-2019			
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):			
	22-JUL-2024			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
HDC34-18	NO			"ZPF000000000131723", "\$\$HDC34- 18"			
HDC34-24	NO			"ZPF000000000131728", "\$\$HDC34- 24", "8B.102.00"			
HDC36-18	NO			"ZPF000000000131719", "HDC36-18- LD", "HDC36-18-L"			
HDC36-24	NO	•		"ZPF00000000131726"			·

Part Number(s) being Modified:

Part Number	Part Discontinued	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
HDC34-18		Diaming		"ZPF000000000131723", "\$\$HDC34- 18"	Trainisc:	Ture Humber(5)	Difference
HDC34-24	NO			"ZPF000000000131728", "\$\$HDC34- 24". "8B.102.00"			
HDC36-18	NO			"ZPF000000000131719", "HDC36-18- LD", "HDC36-18-L"			
HDC36-24	NO			"ZPF00000000131726"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
HDC34-18	NO			"ZPF000000000131723", "\$\$HDC34- 18"			
HDC34-24	NO			"ZPF000000000131728", "\$\$HDC34- 24", "8B.102.00"			
HDC36-18	NO			"ZPF000000000131719", "HDC36-18- LD", "HDC36-18-L"			
HDC36-24	NO			"ZPF000000000131726"			